


60034 Door Stop

Not to scale





Overview

60034 skirting door stop

- Solid stainless steel
- Rubber buffer
- Concealed fixing

Maintenance

- To be carried out by an approved specialist only
- At least once a year check for tolerance and wear and tighten screws that may have become loose
- If for any reason the products fail due to a defect in manufacture contact us and we will advise on the replacement procedure

Certification

NA

Performance Test

NA

Please note:

Aspex reserves the right to change specification without notice.